



See online
technical sheet

/ TP57

Leakage multimeter clamp



/ Standards

IEC 61010 - 1 / IEC 61010-2 / IEC 61010-2-032 CAT III 600 V

/ Use

The TP57 clamp-on meter is the ideal tool to detect insulation faults and untimely tripping of RCDs caused by leakage currents.
It also provides all the functions of a clamp-on multimeter.

/ Technical specifications

RMS measurement

- resolution : 10 μ A
- strong immunity to spurious currents : 70dB
- 50/60Hz harmonic filter
- current : 30 μ A to 100A AC
- AC/DC voltage : 0.1V to 600V
- frequency : 5Hz to 1kHz
- resistance : 0.1 Ω to 1k Ω
- audible continuity : <35 Ω
- backlit display : 10,000 counts
- functions : max. and Delta; display memorization
- battery life indicator light, automatic power off

Supplied with 1 set of 4 mm diameter elbowed leads in red/black with 4 mm diameter contact points, 1 set of 2 x 1.5 V batteries (AAA or LR3) and 1 carrying case

Advantages

To check leakage currents quickly and locate insulation faults in live installations.